

**Fig-1**

File Edit View Favorites Tools Help

Back ▾ ➡ Search ☆ Favorites

Address http://www.spareparts.com/

---

32 — MFG. Part Number:

44 — Barcode:  Critical: ☒ 54 Sheet:  58 Detail:

26 — Keyword:

28 — Part Desc:

30 — Remarks:

56 Operator Name:  64 Dept:

68

66 — Work Station:  40 — Vendor Name:

70 — Drawer:  38 — Vendor Part Number:

62 — Plant:  46 — Vendor: VENDOR Unit Cost:  50

76 — Submit

**Fig-2**

80

File Edit View Favorites Tools Help

Back

Forward

Search

Favorites

Address

http://www.spareparts.com/

32

MFG. Part Number:

68

Operator Name:

40

Vendor:

26

Keywords:

ALL KEYWORDS

Station:

38

Vendor Part Number:

62

Plant:

LTP-LIVONIA TRANSMISSION PLANT

NASUP-NORTH AMERICAN SUPPLIERS

REP-ROMEO ENGINE PLANT

TEST-TEST PLANT FOR DEMO

64

Department:

ALL DEPARTMENTS AT LTP

0028A-LTP-REHAB MAINTENANCE

0028B-LTP-CIM LAB MAINTENANCE

0039A-LTP-N106 MAINTENANCE

44

Barcode:

OR

82

Search

**Fig-3**



92

File Edit View Favorites Tools Help

Back ▾ ▸ Search ☆ Favorites

Address <http://www.spareparts.com/>

32 MFG. Part Number: 44 Barcode: 52 Critical: 54 Blue Print Num: 58 Detail: 58

26 Keyword: 56 Sheet: 64 Dept: 64

28 Part Desc: 40 Operator Name: 68 Adjust On-Hand Quantity 110

30 Remarks: +1 -1

66 Work Station: Vendor Name: 50 Unit Cost: 100


70 Drawer: Vendor Part Number: 46

62 Plant: Vendor: VENDOR Unit Cost: 50

96 Plant Search 94 Global Search 38

Historical Usage

**Fig-5**



**Fig-6**